DIY REFIT BILL	CAPE DORY 25 (1981, Hull No. 82)
DDOIECT	TACKC

* Estimates. Costs include safety equipment (gloves, goggles, respirators) and solvents.

MUJECI

INTERIOR

SEALING

WIRING

PLUMBING

BOTTOM JOB

TOTALS

MAKEOVER

DECK RECAULKING/

EXTERIOR WOOD

APE DORY 25 (1981,	Hull	No.	825)	
	TACVC				

CACHI

Removed old varnish; repaired toerail; repaired coaming

at seam; replaced companionway pull and teak runners

outboard of companionway slide

Rebuilt bulkheads, settees, V-berth, companionway steps/ice

box access, nav table, galley, and shelves, using 6 sheets teak

veneer and marine ply from Teakdecking Systems, re-used old

trim; added insulation to ice box; built and installed cabin sole

Stripped out old adhesive with an awl and re-sealed all

metal-teak and teak-deck connections

Replacing wiring with marine grade; adding mast light;

added bow and stern lights with welded-on pulpit brackets;

added shorepower hookup in lazarette

Installed new Jabsco head pump, Whale gusher pump, 8-gal.

fiberglass holding tank, deck washdown pump, deck fills &

pumpout; replumbed head, adding Y valve and vented loop;

replaced lines; added freshwater line

Removed old bottom paint; filled holes and faired keel; put on

3 coats of antifouling with extra coats at waterline

CAPE	DORY	25	(1981,	Hull	No.	825

APE	DORY	25	(1981,	Hull	No.	825)

APE DORY 25	(1981, Hull No. 825)	

MAN

HOURS*

50 hours

200 hours

25 hours

35 hours

(est.)

60 hours

35 hours

405 hours

PROJECT

COST*

\$35

\$1,000

\$100

\$400+

\$400

\$500

\$2,435

DIY REFIT BILL	CAPE DORY 25 (1981, Hull No. 825)

CAPE	DORY	25	(1981,	Hull	No.	825)