


## HITS AND MISSES



**MISS:** Mediocre ventilation.

**HIT:** Plenty of headroom.

**HIT:** V-berth (above) offers spacious sleeping quarters.

**MISS:** Side-opening V-berth hatches stymie ventilation at anchor.



**HIT:** Airy main salon.

**MISS:** Cabin sole panels don't latch down.



**HIT:** Cook gets a hatch and two opening ports.

**MISS:** Handholds, not tube lights, belong up here.

**HIT:** Roomy salon is great for socializing.

**MISS:** Front-loading fridge and freezer are relatively inefficient.

**HIT:** L-shaped galley is ergonomically arranged.

**MISS:** Bi-fold doors at companionway are too wimpy for our taste.