

PRODUCT ALERT

ACR Recalls Select Batches of EPIRBs

ACR Electronics Inc. is voluntarily issuing a limited recall of its GlobalFix iPRO EPIRBs. Through its ongoing quality assurance processes, ACR had discovered that some of the witness seal tabs used in the manual activation of the GlobalFix iPRO required the application of excessive force to put the switch into its correct position. The water activation feature works separately and is not affected by the manual switch.

This condition, according to ACR Electronics, could exist in a maximum of 400 units built within serial number range of 1,000 to 1,699. The 400 units could be either the P/N #2846 Category I (automatic deploy) or P/N #2848 Category II (manual deploy) model. (iPROs with serial numbers outside of this limited recall range are not affected by this notice.) The company has asked anyone owning a GlobalFix iPRO falling within the suspect serial-number range to contact ACR's Customer Service Department immediately at 954/862-2110 or e-mail nbuckle@acrelectronics.com.

