

HITS AND MISSES



HIT: Curved companionway steps.

MISS: Fold-down locker over stove inaccessible while cooking.



HIT: Oversized opening ports improve cabin ventilation.

MISS: Unexceptional joinery.



HIT: Easy hardware access

HIT: Polished stainless chainplates

MISS: Stuffy aft cabin

HIT: Keel-stepped carbon-fiber spar

MISS: Tight, uncomfortable, sea berths

MISS: Tight fitting sole thwarts inspection

HIT: The one-shot molding process keeps the deck light and the overhead clean.

MISS: The aft cabin setup eliminates any modicum of privacy that may exist on a 33-footer.