


Step One: Strip a Test Patch

Sometimes the type of paint to be removed or the required dwell time (how long the stripper should be left on) is unknown. Testing a small area helps determine the time required to remove your particular paint. Generally, the more coats of paint, the longer the dwell time. Testing also helps determine whether the gelcoat is suitable for stripping.



Pettit Bio-Blast