

## A CLOSER LOOK

### Radio Autopsy

A peek at the innards of two radios after the submersion test shows how well the TC-11-treated product (top) fared, in comparison to the one coated with LPS-1 (bottom). The TC-11 test radio was the only one without corrosion on its battery terminals. The LPS-1 radio suffered corrosion to all of its battery terminals and had white deposits inside its case. The zoomed-in photos at far right show the radios' volume-control potentiometers, which were reduced to a chunk of rust on all 10 test radios.

