



The photo above left shows the deterioration of the chain sections. The difference between those sections suspended in shallow water and those buried in mud is obvious. These links have come a long way from the shiny ones we dropped 12 months before (photo, above right).

proof coil

Acco BBB

high test