


## A CLOSER LOOK



1

**1.** Testers had a hard time mounting the Honda test engine on the Fulton MB 1820. The Honda's hinged handle interfered with bracket's lifting handle.

**2.** The Garelick 71091 employs a spring mechanism and unique safety knobs to hold the bracket in position.

**3.** A stainless safety strip hooks on a bolt to hold the Garelick 71092 in its up position.



2



3