

WATERPROOF BEARING

CORROSION BLOCK

NOALOX

NO-OX-ID

BOESHIELD

GREASE

Excellent

Very good

Poor

Poor

Poor

NOTES

Clean, no corrosion

Grease still visible on #1,

little corrosion on #2

Very poor condition

Very poor condition

The worst condition

TEST REPORT	TINNED COP CORROSION		WITH
REATMENT	RESISTANCE	APPEARANCE	

< 0.05 ohms

< 0.05 ohms

< 0.05 ohms

< 0.05 ohms

< 0.05 ohms